



Ford
19+ Ford Ranger
20 Inch Light Bar
Installation Instructions



Heretic

1168 West 500 North Suite 500
Centerville UT, 84014
801-725-4824
Support@hereticstudio.com

Step 3: Once the cover is free, there are two plugs that must be disconnected. Set bumper cover aside.



Step 4: With a Standard screwdriver (flathead), bend all the bumper cover mounting clips back to original condition. Before picture on left below, after on right.



Step 5: Using 21mm socket wrench, remove OEM frame nut circled below, place bracket, and lightly tighten nut. Passenger side is pictured below. Repeat for driver's side.



Step 6: Place the lightbar into the opening. Thread in the 1/4" hardware and lightly tighten with 7/16" socket wrench.

Step 7: Once satisfied with the positioning of the light, tighten the 1/4" hardware, then tighten the large factory nuts from step 5.

Step 8: With the plastic bumper cover near the mounting location, connect the safety sensor plugs and gently begin to press the cover back into the mounts. Work around the cover and refer to the image under step 2 for the mount locations.

Your install is now complete! Thanks for choosing Heretic!



@hereticstudio

Heretic
BEYOND LUMENS