

ALTERUM

LEATHER CENTER CONSOLE COVER

(2007-2013 SILVERADO/SIERRA)

INSTALLATION INSTRUCTIONS

CONTENTS

(1) Center Console Arm Rest
Cover
(1) Center Console Lid Latch

TOOLS REQUIRED

T-20 Torx Screwdriver
Phillips Screwdriver
Plastic Pry Tool

SKU S126720-S126722


ALTERUM

STEP 1



Open the center console lid. Remove (4) T-20 Torx screws from the plastic panel on the lid.


STEP 2



Using a plastic panel pry tool, remove the plastic panel from the center console lid.

ALTERUM

STEP 3



Remove (4) Phillips screws from the hinge going through the center console lid. Remove the lid from the vehicle.

STEP 4



Remove the (2) pre-installed Phillips screws in the new center console lid, then install the provided center console latch into the lid. Tighten the screws until secure, do not over tighten.

ALTERUM

STEP 5



Install the new center console lid to the vehicle re-using the original (4) Phillips head screws. Tighten until secure, do not over-tighten.

STEP 6



Install the original plastic panel to the new center console lid re-using the original (4) T-20 Torx screws. Tighten until secure, do not over-tighten.

ALTERUM



STEP 7

Close center console lid and ensure latch functions normally.

Installation is now complete.