

# ***ALTERUM***

---

## **LEATHER CENTER CONSOLE COVER**

(2007-2013 SILVERADO/SIERRA)

---

### INSTALLATION INSTRUCTIONS

#### CONTENTS

---

(1) Center Console Arm Rest  
Cover  
(1) Center Console Lid Latch

#### TOOLS REQUIRED

---

T-20 Torx Screwdriver  
Phillips Screwdriver  
Plastic Pry Tool

SKU S126720-S126722

# ALTERUM


---

## STEP 1



Open the center console lid. Remove (4) T-20 Torx screws from the plastic panel on the lid.

## STEP 2




Using a plastic panel pry tool, remove the plastic panel from the center console lid.

# ALTERUM

---

## STEP 3



Remove (4) Phillips screws from the hinge going through the center console lid. Remove the lid from the vehicle.

## STEP 4



Remove the (2) pre-installed Phillips screws in the new center console lid, then install the provided center console latch into the lid. Tighten the screws until secure, do not over tighten.

# ALTERUM

---

## STEP 5



Install the new center console lid to the vehicle re-using the original (4) Phillips head screws. Tighten until secure, do not over-tighten.

## STEP 6



Install the original plastic panel to the new center console lid re-using the original (4) T-20 Torx screws. Tighten until secure, do not over-tighten.

# **ALTERUM**

---



---

## **STEP 7**

Close center console lid and ensure latch functions normally.

Installation is now complete.